

**Sewage Disposal System Maintenance Inspection Program Summer 2018**

*Jack Lake Initial Inspections: 04/24/2017 TO 07/29/2017*

Year	2017
Site Visit From	04/24/2017
Site Visit To	08/29/2017
No Information	0
No Plumbing	0
System Acceptable	30
Upgrade Recommended	5
Upgrade Required	13
More Information	64
Health Hazard	0
<b>TOTAL Site Visit Inspections</b>	<b>112</b>
<b>Total Number of Properties on Jack Lake</b>	<b>112</b>

<u>Calculation Breakdown</u>		
System Acceptable	30/112	X 100= 27%
Upgrade Recommended	5/112	X 100= 4%
Upgrade Required	13/112	X 100= 12%
More Information	64/112	X 100= 57%

**Figure 18: Sewage Disposal System Maintenance Inspection Program- Jack Lake Initial Inspection Results**

